ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ ਹੁਸ਼ਿਆਰਪੁਰ।

ਵੱਲ

The Paincipal Bota many Convent Sx Sec School Kang may Hariana Hoskiaspe

2842

ਮਿਤੀ 23-12-19

ਇਸੂ ਆਫ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਫਾਰ ਦੀ ਯੀਅਰ-----

ਹਵਾਲਾ :-

Application ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ

ਉਪਰੋਕਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ----- ਉਪ ਮੰਡਲ ਨੰ:---ਹੁਸ਼ਿਆਰਪੁਰ ਵਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ ਦੇਖਣ ਤੋ ਠੀਕ ਠਾਕ ਲੱਗਦੀ ਹੈ ਅਤੇ ਸਾਲ ———— ਲਈ ਸੁਰੱਖਿਆਤ ਪਾਈ ਗਈ ਹੈ ਅੱਗੇ ਤੋਂ ਹੇਠ ਲਿਖੀਆਂ ਹਦਾਇਤਾਂ ਵੱਲ ਵਿਸ਼ੇਸ ਧਿਆਨ ਦਿੱਤਾ ਜਾਵੇ : -

- ਬਿੱਲਡਿੰਗ ਦੀਆਂ ਛੱਤਾਂ ਅਤੇ ਆਲੇ ਦੁਆਲੇ ਪਾਣੀ ਨਾ ਖੜਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ ।
- ਜੇਕਰ ਇਮਾਰਤ ਵਿੱਚ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇੜ ਵਗੈਰਾ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸ ਦੀ ਰਿਪੇਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ ।

ਨਾਲ ਨੱਥੀ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵਲੋਂ ਕੋਈ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨੀ ਹੋਵੇਂ ਤਾਂ ਉਸ ਦੀ ਮੰਨਜੂਰੀ ਇਸ ਮਹਿਕਮੇ ਪਾਸੋਂ ਲਈ ਜਾਵੇ।

ਨੱਥੀ / ਨਕਸਾ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ vinicial Division ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖ਼ਾ P&R Branch ਹੁਸ਼ਿਆਰਪੁਰ। 🖯 Upshiarpur (D.B.)

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਮਿਤੀ ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ -

-- ਉਪ ਮੰਡਲ ਨੰ:-

ਹੁਸ਼ਿਆਰਪੁਰ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰਬਰ : ----- ਮਿਤੀ ----- ਦੇ ਹਵਾਲੇ ਅਧੀਨ ਭੇਜਿਆ ਜਾਂਦਾ

ਨੱਥੀ / X

Executive Engineer, ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰinicial Division ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮਿ/ਸਥਿਆ &R Branch ਹੁਸ਼ਿਆਰਪੁਰ Loshiarpur (b.s.)

True translation from Punjabi to English

From

Executive Engineer, Provincial Division, B & R Branch, Hoshiarpur.

To

The Principal,
Baba Manjh Convent Sr. Sec. School,
Kang, Mai, Hariana, Hoshiarpur
No. 2842 Dated: 23-12-19

Subject: Issue of Building safety certificate for the year 2019-20.

Reference: Your letter No. Application dated

The inspection of the building of above noted school has been conducted by Sub Divisional Engineer Construction Sub Division no. 3 Hoshirpur and building on appearance seems good and is found safe for the year 2019-20. In future the special attention be paid to the following instruction:

- 1. The water should not be collected on the roofs and around the building
- 2. If any kind of cracks occurred in the building then said area be vacated immediately and it be got repaired immediately.
- 3. Apart from the attached map if any further construction is to be made then its permission be taken from this department.

Attached./Map Sd/-

MOTARY

MOSTS-7923

MONE SHENSFER

MONETURE

M

Executive Engineer Provincial Division P.W.D. B & R Branch Hoshiarpur (DB)

Endst. No. Dated

Copy of above is being sent to Sub Division Engineer

Construction Sub Division No. 3 Hoshiarpur under their

letter No. ____ dt. ____.

Attached /x

Executive Engineer Attested True, Translation of the Documents produced in original in PurijabitAirdu

JARNAIL SINGH SEHGAL Notary Public Hoshiarpur (Fb.) India (M) 9815979333 Provincial Division P.W.D. B & R Branch Hoshiarpur (DB)

261219