ਕ ਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ ਹੁਸ਼ਿਆਰਪੁਰ ।

ਵੱਲ

The Proincipal Kang mai

541

Fred 24/05/2023

हिमां :-ਇਸੂ ਆਫ ਬਿਲਡਿੰਗ ਸੈਫਟੀ ਸਰਟੀਫਿਕੇਟ ਫਾਰ ਦੀ ਯੀਅਰ--- 2023-24

ਹਵਾਲਾ :-ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ-----Application

ਉਪਰੋਕਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਨਿੱਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ-ਮੰਡਲ ਨੌ:-3-- ਹੁਾਸ਼ੇਆਰਪੁਰ ਵਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ ਦੇਖਣ ਤੋਂ ਠੀਕ ਠਾਕ ਲੱਗਦੀ ਹੈ ਅਤੇ ਸਾਲ <u>ਵਿਕਟੇਤ ਦ</u> ਲਈ ਸੁਰੱਖਿਆਤ ਪਾਈ ਗਈ ਹੈ ਅੱਗੇ ਤੋਂ ਹੇਣ ਲਿਖੀਆਂ ਵਾਇਤਾਂ ਵੱਲ

- ਬਿਲਡਿਗ ਦੀਆਂ ਛੱਤਾਂ ਅਤੇ ਆਲੇ ਦੁਆਲੇ ਪਾਣੀ ਨਾ ਖੜਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ
- ਜੇਕਰ ਇਮਾਰਤ ਵਿੱਚ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇੜ ਵਗੈਰਾ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸ ਦੀ ਰਿਪੇਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ ।
- ਨਾਲ ਨੱਥੀ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵਲੋਂ ਕੋਈ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨੀ ਹੋਵੇਂ ਤਾਂ ਉਸ ਦੀ ਮੰਨਜੂਰੀ ਇਸ ਮਹਿਕਮ ਪਾਸੋਂ ਲਈ ਜਾਵੇ। तंषां / उवमः :

ਪਿੱਠ ਔਕਣ ਨੰ: ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਹੁਸ਼ਿਆਰਪੁਰ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰਬਰ : ------ ਮਿੜੀ ----- ਮਿੜੀ ----- ਦੇ ਹਵਾਲੇ ਅਧੀਨ ਭੌਜਿਆ ਜਾਂਦਾ ਹੈ ।

ठॅघो / X

ਪ੍ਰਾਤਕ ਮੁਡਾਲ਼ ਤੂੰ ਤੂੰ ਜ ਸਾਖਾ ਹੁਸ਼ਿਆਰਪੁਰ 🕡

ਭ-ਅਕੀ ਉਪ ਮੰਡਲ ਨੇ:-3

ਕਾਰਜਕਾਰੀ ਦਿਜੀਨੀਅਰ ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ ਹੁਸ਼ਿਆਰਪੁਰ

Baba Manjh Convent School

(School no. 20219 | Aff. code 1630224) Kang Mai, Hariana, Hoshiarpur

Managing Committee Baba Manih veni Echooi (Heshiarpur)

From s-

Executive Engineer, Sub-Divn , Soil Cons.Branch, Hoshiarpur.

To

The Principal, Baba Manj Convent School, Kang Mai.

No.541 dt. 24.5.2023.

Subject: Issue of Building Safety Certificate for the year, 2023-24.

Ref: As per your letter No . Application. dt.

The building of the school as per inspection of Sib-Divisiona Engineer(Construction) Mandal No.3, Hoshiarpur, done and found found that building is fit seen and the same is found fit for the financial year, 2023-24 is in every respect, and the following instructions must be following:-

- i) That the water should not be gathered arround the building.
- ii) That if there is any kind damage occurred to thw walls etc. then it must should be vacated & repair the same.
- iii) That if the concerned school intend to do the further construction then the approval of the same should be taken from the deptt.

Enclosed: Map.

Sd/-Executive Engineer, Sub-divn.No.3,/Branch, Hoshiarpur.

Endst.No. Dt.

Gurpreet Kaur

7000 No. 9036

Copy forwarded to Sub-Divn Engineer/Construction , Sbb-Divn No.3, Hoshiarpur, as per their letter No.62 dt.18.5.2023.

Principal
Baba Marijh Convent School
(School no. 20219 | Aff. code 1630224)
Kang Mai, Hariana, Hoshiarpur

Sd/-Executive Engineer, Sub-Divn.Seil Cons.Branch, Hoshiarpur.

-: Attested to be a true translated copy from Punjabi to English:-

Attesped True Photos Translation Copy of the Documents Produced

GURPREE NOTARY Hosman

(M) 97

HIGH COMMISSION EMBASSY

HIGH COMMISSION EMBASSY

Managing Committee Baba

Managing Committee Baba Manih Convent School (Roshiarour)